

remove all branches renew and run internally where possible

remove all branches renew and run internally where possible

renew gutter & downpipes in CI or Aluminium

remove satellite dish and cable

cables adjusted by A College

remove all

CONTRACTORS ACCESS POINT TO 2ND STOREY

scaffold platform access to holding area

Revision	Date
<b>DALBY ARCHITECTURE</b>	
Client	Ardingly College
Job Title	<b>2nd Floor South Wing (Old Hilton) Refurbishment &amp; Alterations</b>
Drawing Title	Conversion of dormitory wing to classrooms & tutor rooms <b>East &amp; West Elevations services work</b>
Drawing Status	<b>Construction</b>
Drawn by	Checked by Date
NAD	
Scale	Date
1:50	14.05.08
Drawing Number	Revision
26316 / 49	

